

Figure 1




Figure 2




Table 1 - Normalized "step-down" ratio design criteria

Nago	Input Z	nput Z Section 1	Section 2	Section 3	Section 4	Section 2 Section 3 Section 4 Section 5	Outnut 7
1.50	1.0	0.376	0.250	1 50n	1 500	2 000	0.667
2.00	1.0	0.125	2			2000	0.00
2.25	1.0	0.125		1	2000		0.00
2.50	1.0	0.150			1 500	- 10	0.444
3.00	1.0	0.125		100	1 500	1,	7
3.50	101	0.150		0.750	1,000	2.000	٦١٥
4 חח	-	100		0.7.0	000.	2.000	0.280
		0.123	ľ	7.000	U.5.U	0.668	0.250
000		0.083		1.000	1.000	1.500	0.167
a.uu	1.0	0.063	0.125	2.000	0 200	0.668	175

Table 2 - Normalized "step-up" ratio design criteria

			-				
Ratio	Input Z	Section 1	Section 2	Section 1 Section 2 Section 3 Section 4 Section 5 Output Z	Section 4	Section 5	Output Z
1.50	0.667	2.000	1.500	1.500	0.250	0.376	1.0
2.00	0 200	2 000	0.500	1.000	2.000	0.125	1.0
2.25	0.444	1 500	2.000	0.333	1 500	0.125	1.0
2.50	0.400	2.000	1 500	1 000	0.250	0 150	1.0
3.00	0.333	2.000	1.500	1.000	0 250	0.125	10
3 50	0.286	2.000	1 500	0.750	0 150	0.150	10
4 00	0.250	9990	1 500	2.000	0.125	0.125	1.0
9	0 167	1 500	1 000	1.000	0.125	0 083	10
8 00	0 125	899 0	0.500	2.000	0.125	0.063	10

## Figure 4

10






Figure 6




Figure 7